



# FORTUNE MINERALS LIMITED

140 Fullarton Street, Suite 1902, London, Ontario, Canada N6A 5P2  
Tel. 519-858-8188 ~ Fax. 519-858-8155

June 9, 2010

Mr. Arthur Pape  
Pape Salter Teillet  
546 Euclid Avenue  
Toronto, Ontario  
M6G 2T2 CANADA

Dear Mr. Pape:

Fortune has reviewed of the revised map titled The Developer's Wishes for a Road, and requests that the following corrections be made.

First, the road alignment required for the NICO Project is correct only up to the point 19 kilometres north of the Whati road junction that is approximately 10 kilometres east of Whati. It should also be noted that the alignment shown in the map was proposed by the GNWT DOT for the realignment of the winter road to an all land route between Highway 3 and Gameti.

Second, the road alignment and corridor beyond kilometre 19 should be removed. Fortune Minerals Limited has not proposed a road to Gameti and does not intend to propose any road in the future because this has no effect on the project. This alignment was part of the DOT proposed alignment for the all land realignment of the current winter road.

Please make these corrections to the map so the Review Board has the correct information.

Sincerely,

A handwritten signature in black ink, appearing to read 'T. Rinaldi'.

Thomas R. Rinaldi  
Vice President Operations  
Fortune Minerals Limited