



Tłįchǫ All-Season Road Project: Conditions along route in June 2014





First 5 km











Near KM 11.5

Sandy

Near KM 20





Water Crossing 6



Near KM 12.5 Wellestablished Trail





Near KM 23

Near KM 23 – Burn Area Behind

Near KM 26

2014 Forest Fire Season Impacted First 38 km of Road Fire passed through this area after June 2014 field trip



Near KM 27.5





Near KM 37 – 1994 Burn

Near KM 40





Near KM 36 – Willow/Birch Overgrowth occurs in small areas along route

Near KM 39





km 36.





Duport River



3² 4 5 1















Near KM 43.5 Crossing 9 KM 46



To Whatì















Crossing 10 looking north

Boggy Sections

Near KM 52



Near KM 47.5

Grassy

Near KM 52













Helicopter in front of route

Looking east

Wide floodplain

Water Crossing 12 – KM 58



Erosion on Hill



Looking back



Near KM 61.5




Near KM 63.5













Near KM 67.5

Near KM 70





km 74....

km Tž

Km 68



Near KM 68

Near KM 70 - downhill





James River

To What

Crossing 14 – KM 71







Rocky along cleared route starting here →




Near KM 72.5



km 76km 74km 72-









Near KM 78.5

Entering:

Near KM 85.5





Frank's Camp Near KM 78



Near KM 81.5 **Tłįchę** Lands

Near KM 85.5











La Martre bridge location



