

Cantung Mine ***Abandonment & Restoration Plan***

November, 2001

Submitted to:
North American Tungsten Corporation Ltd.

NORTH AMERICAN TUNGSTEN UNION
MINING

Prepared by:
EBA Engineering Consultants Ltd.

**EBA Engineering
Consultants Ltd.** 

94

**NORTH AMERICAN TUNGSTEN CORPORATION
LTD.**

**CANTUNG MINE ABANDONMENT AND
RESTORATION PLAN**

November, 2001

File: 0701-01-14862

EBA Engineering Consultants Ltd.

CANTUNG MINE
ABANDONMENT AND RESTORATION PLAN

Prepared by:

EBA ENGINEERING CONSULTANTS LTD.
550 – 1100 Melville Street
Vancouver, B.C.
V6E 4A6

Submitted To:

NORTH AMERICAN TUNGSTEN CORPORATION LTD.
1188 West Georgia Street
Vancouver, B.C.
V6E 4A2

Project No. 0701-01-14862

November, 2001

TABLE OF CONTENTS

	<u>Page</u>
1.0 INTRODUCTION.....	1
1.1 TERMS OF REFERENCE.....	1
1.2 OBJECTIVES OF THIS PLAN.....	1
1.3 SCOPE AND ORGANIZATION.....	2
2.0 CLOSURE PLANNING	4
2.1 CLOSURE PHILOSOPHY	4
2.2 CLOSURE SCENARIO.....	4
2.3 RELATED INVESTIGATIONS TO DATE.....	5
3.0 PROPERTY DESCRIPTION.....	6
3.1 GENERAL.....	6
3.2 LOCATION AND ACCESS.....	6
3.3 STATUS.....	6
3.4 HISTORY.....	6
3.5 SITE FACILITIES	8
3.6 OWNERSHIP	11
4.0 ENVIRONMENTAL CONSIDERATIONS.....	12
4.1 GEOLOGY	12
4.1.1 Regional.....	12
4.1.2 Deposit Geology.....	12
4.2 TOPOGRAPHY.....	13
4.3 CLIMATE.....	13
4.4 VEGETATION AND LAND USE.....	15
4.5 SITE WATER CHEMISTRY.....	15
4.5.1 Surface Water.....	15
4.5.2 Groundwater.....	16
4.6 ACID ROCK DRAINAGE POTENTIAL.....	16
5.0 MINE WORKINGS.....	17
5.1 OPEN PIT WORKINGS.....	17
5.1.1 Description.....	17
5.1.2 Closure Issues.....	17
5.1.3 Closure Measures and Investigations.....	17
5.2 UNDERGROUND WORKINGS.....	18
5.2.1 Description.....	18
5.2.2 Closure Issues.....	18
5.2.3 Closure Measures and Investigations.....	20
6.0 PROCESSING FACILITIES.....	21
6.1 DESCRIPTION	21
6.2 CLOSURE ISSUES	21
6.3 CLOSURE MEASURES.....	21
7.0 MINE WASTE MANAGEMENT FACILITIES.....	22
7.1 WASTE DUMPS.....	22
7.1.1 Description.....	22
7.1.2 Closure Issues.....	22
7.1.3 Closure Measures and Investigations.....	23
7.2 TAILINGS.....	24
7.2.1 Description.....	24
7.2.2 Closure Issues.....	26
7.2.3 Closure Measures and Investigations.....	31
8.0 INFRASTRUCTURE.....	33
8.1 TOWNSITE.....	33
8.2 ROADS AND AIRSTRIPS.....	33
8.3 FUELS AND CHEMICALS.....	34

9.0 CLOSURE..... 35
 9.1 MONITORING AND MAINTENANCE 35
 9.2 COSTING..... 35
10.0 REFERENCES..... 36

FIGURES

Figure 1 CanTung Mine Map 7
 Figure 2 CanTung Mine Site Plan..... 9
 Figure 3 Aerial Photo of CanTung Mine Site..... 14

PHOTOS

Photo 1 Overview of the CanTung Mine and Townsite With Tailings Pond 3 in
 the Background 10
 Photo 2 view of the Tungsten Townsite with the Millsite to the Right 10

APPENDICES

APPENDIX A Closure Costing Spreadsheet